

BORING	PRØVE (lab)	DYBDE	PRØVEBESKRIVELSER (Forkortet)	SIGTEANALYSE (Gennemfald)			U	SANDÆK- VIVALENT	KALKIND- HOLD	KORNDEN- SITET (0-0,075 mm) (0-16 mm) ρ_s t/m ³	NATURLIGT VANDIND- HOLD W_{nat} %	STANDARD PROCTOR		W_{nat} - W_{opt} %	PLASTICITET		CBR
				0,002 mm %	0,075 mm %	2 mm %						W_{opt} %	ρ_d max t/m ³		WL %	IP %	
nr.	nr.	m	Jordart karakterisering	frost			$\frac{d_{60}}{d_{10}}$	SE %	(0-1 mm) ka %								
0955	5001 5002	0,5 - 1,0	SAND, mellem, enk. gruskorn, sv. siltet	kalkf. - ?		8,7	94	4,5				6					
		1,0 - 2,0	SAND, fint - mellem	do. -		8,3	98	4,2				4					
	5012		SAND, fint - mellem	kalkf. -		8,9	96	4,6				4					
1210 1220 1230 1240 1260 1270 1280 1300 1310 1320 1330 1335			AFGRAVNINGSTRÆKNING MV. ST. 11.90 - 13.54														
	5307	1,0 - 2,0	SAND, mellem	kalkf. -		6,0	97	4,0	71			7	9,7	1,86			
	5318 5320	0,5 - 1,0	SAND, mellem	kalkf. -		2,0	100	2,9	85			8					
		1,0 - 2,0	SAND, fint - mellem, siltet, enk. gruskorn	do. + ?	1	14,3	93		64			10,5	8,9	1,94			X
	5329 5330	0,5 - 1,0	SAND, mellem	kalkf. -		6,2	93	3,8	78			8					
		1,1 - 2,0	SAND, mellem, sv. siltet, enk. gruskorn	do. + ?	2	15,7	84		32			9					
	5342	1,1 - 2,0	SAND, fint - mellem	kalkf. -		16,8	96		30			8	8,5	1,92			
	5360 28 30	0,5 - 1,0	SAND, mellem, enk. gruskorn	kalkf. -		8,2	85	5,1	67			6					
		1,0 - 1,6	SAND, mellem, sv. gruset	kalkf. - -		14,7	88		24								
	5371 5372	0,5 - 1,0	SAND, fint - mellem, sv. leret, sv. gruset	do. - -	2	20,7	92		18			8					
		1,0 - 1,6															
	5371 5372	0,6 - 1,0	SAND, fint - mellem, enk. gruskorn	kalkf. -		5,9	87	3,3	71			4					
		1,0 - 2,0	SAND, mellem	do. -		7,3	91	4,5	46			4	9,2	1,91			
	5392 5393	0,4 - 1,0	SAND, mellem, gruset	kalkf. -		11,1	65		27			4					
		1,0 - 1,8	SAND, mellem, gruset	do. -		8,5	72	10,8	30			5	6,6	2,10			
	5442 5446	1,1 - 2,0	SAND, mellem, velsorteret	kalkf. - -		2,0	100	2,0	85			4					
		3,1 - 4,0	SAND, mellem - groft	do. - -		2,3	97	3,9	86			6,5	11,5	1,81			
	5457 5461	1,1 - 2,0	SAND, mellem	kalkf. -		3,3	95	2,9	87			4	11,3	1,76			
		3,0 - 3,8	SAND, fint - mellem, siltet	do. +		18,4	98		22			12,5	9,3	1,97			
	5472 5482	1,1 - 2,0	SAND, fint, velsorteret	kalkf. - ?		9,4	99	2,2	33			8					
		5,0 - 6,0	SAND, fint - mellem, sv. siltet	do. - ?	5	15,2	98		22			11	9,8	1,89			
	5497	3,1 - 4,0	SAND, fint	kalkf. -		8,9	97	2,8	40			13,5	12,0	1,75			

X CBR-forsøg er udført. Der henvises til forsøgsoversigterne i Geotekniske Data 2.

MOTORVEJEN A-STRUP - D-STRUP		1234 B-STRUP - C-STRUP	
Afgravningsstrækning Motorvej st. 9.50 - 9.72 og 11.90 - 13.54		Tegn.: BVE	Kontr.: MRN
		Godk.: JILA	Dato: 25.03.2015
 Vejdirektoratet		Bilag nr.: 2.16	